

14032104

REF.	DISTANCE	DESCRIPTION
l.	133.60'	NW corner of one-story frame
2.	35.92	PK nail S PwP#39-780 12"up
3.	119,95	SE corner of porch for house
4.	1332.25	Due E 1/4 mile to railroad spike
5.	44.33'	Road nail N PwP#14-810 2"up
6.	137.46'	Road nail N PwP#1-809 2"up
7.	671.41'	Due W to C/L of Lake Road 3800 W (survey mark nail over
		stone under clay tile)

Corner originally set as a post in 1820 by Wm. B. Laughlin with the following witnesses: 12" beech bearing north 33 degrees, thence east 18 links; and a 8" buckeye bearing south 20 degrees, thence west 20 links. (M.C.Atlas p. 5) A survey by H.B.Fatout on September 1,1885 indicates no stones or witnesses. (Perry Legal Book p. 33) A survey by John Coyner on January 18,1900 indicates a stone set with no witnesses. (Perry Legal Book p. 64) Corner referenced by Wilcoxen on 12/17/76 and called an iron pin. Corner referenced by Wilcoxen on 5/1/80 and called an iron pin. Corner referenced by Wilcoxen on 5/1/80 and called an iron pin. Corner referenced by Whiteside on 4/11/96 and called a p.k. Nail. Corner referenced by Whiteside on 3/10/01 and called a rebar. Corner excavated by Wilcoxen on 7/12/04 and a rebar was found 4" down. No other points were found. No stone was found. A #205 cast iron Harrison Monument was set in position as the corner.